

RECOMMENDATIONS FOR THE AFTER CARE OF THE NEW KNITWEAR RANGES

1. TURN GARMENT INCLUDING CUFFS INSIDE OUT BEFORE WASHING
2. WARM MAX 40 DEGREE WASH
3. DO NOT USE FABRIC CONDITIONER
4. DO NOT WRING
5. DO NOT TUMBLE DRY
6. DRY FLAT
7. DO NOT IRON